Diagram B: Dimensions and Edges

Rev: 8.02

To aid in identifying dimensions and edges: Please refer to the example below. Additional information can be found on the pages titled "Ordering Guidelines" and "General Information." NOTE: Unless otherwise noted, dimensions are for example only.
Hinge Cutouts and Notch Locations: To assure accuracy, a Detail Drawing of hinge cut outs and holes should also be provided.
Irregular or Curvilinear Edges: (as shown in this example) The maximum and minimum glass dimensions should be provided for each panel, with preferences for any variation between the two extremes also noted.
Glazed Corners: (as at Panels B/C, below) UltraGlas does not miter corners — all edges are fire polished (gently rounded) and can be overlapped or butt glazed. A plan view of such corners is recommended. In areas of deep relief, edges are gradually "eased" (flattened) at the edges, to prevent gaps at glazed joint.



ADDITIONAL INFORMATION: DON'T FORGET TO INCLUDE ALL NECESSARY DESCRIPTIVE INFORMATION (SEE BOTTOM OF DIAG. A)

ULTRAGLAS INC. 9200 GAZETTE AVENUE, CHATSWORTH CA 91311 800 777 2332 — FAX 818 772 8231
E-MAIL: SALES@ULTRAGLAS.COM WWW.ULTRAGLAS.COM